



Weighing Technology

A Higher Level of Precision...A Higher Level of Performance

AFW
SERIES

Heavy Duty Bench & Platform Scale

- Heavy Industrial Use Cast Aluminum Structure
- Stainless Steel Platform Cover
- Strong Steel Pillar
- Optional Wheel Kit Available
- 132 lb to 660 lb Range
- Platform Size 16.7" x 20.6"

Heavy Duty Weighing at an Economy Price

- Rechargeable Battery
- 1" LCD Backlit Display
- lb / kg Keyboard Enabled
- Filter for Animal Weighing



Manufactured by an ISO 9001 certified company.



Model	AFW-F60	AFW-F150	AFW-F300
Capacity	60 kg / 132 lb	150 kg / 330 lb	300 kg / 660 lb
Readability	0.01 kg / 0.02 lb	0.02 kg / 0.05 lb	0.05 kg / 0.1 lb
Divisions	6,000	7,500	6,000
Weighing Units	lb / kg		
Stabalization Time (seconds)	< 2		
Tare Range	To capacity by subtraction		
Power Source	Built-in rechargeable battery or external power adapter (included)		
Construction	Stainless steel platform with heavy duty aluminum structure		
Display	1 inch, 7 segment, wide viewing angle backlit LCD		
Platform Size (W x D x H)	16.7 x 20.6 x 4.5 inches / 425 x 524 x 115 mm		
Overall Dimensions (W x D x H)	16.7 x 29 x 35 inches / 425 x 737 x 889 mm		
Operating Environment	32°~ 104° F non condensing R.H. ≤ 95%		
Net Weight	39 lb / 17.7 kg		
Shipping Weight	47 lb / 21.3 kg		
Options	3 inch wheel kit, Load cell extension cable, Dry cell battery pack		

AFW Series



Features

- Deep skirted stainless steel platter
- Overload and shock protection
- Backlit LCD display with wide viewing angle
- Reads in kilograms or pounds
- Built-in rechargeable battery and external A/C adapter
- Zero tracking
- Automatic power save
- Low battery indicator & charge status light
- Adjustable feet & spirit Level
- In use dust cover for indicator
- Indicator rotates through 135 degrees

Benefits

- Easy to clean for food processing or harsh environments
- Will withstand harsh industrial environments
- Easy to see weight values from a distance, reduces mistakes
- Flexibility of operation
- Portability, minimum 150 hours
- Ensures that you always start weighing from zero
- Conserves battery power
- Alerts you to charge the battery, saving downtime
- Ensures scale can be leveled on uneven working surfaces
- Keeps indicator clear from contamination
- Enables viewing from all angles